



PIM Inspections

PO Box 999, Manly NSW 2095 Phone: 1300 668 594

support@propertyinspectionmanager.com

Schedule 2: Condition report (Outgoing)

How to complete this report

- 1. Three copies, or one electronic copy, of this condition report should be completed and signed by the landlord or the landlord's agent.
- 2. Two copies, or one electronic copy, of the report, which have been completed and signed by the landlord or the landlord's agent, must be given to the tenant before or when the tenant signs the agreement. The landlord or landlord's agent keeps the third copy or an electronic copy.
- Before the tenancy begins, the landlord or the landlord's agent must inspect the residential premises and record the condition of the premises by indicating whether the particular room item is clean, undamaged and working by placing "Y" (YES) or "N" (NO) in the appropriate column (see example below). Where necessary, comments should be included in the report. The landlord or the landlord's agent must also indicate "yes" or "no" in relation to the matters set out under the headings "Minimum standards", "Health issues", "Smoke alarms", "Other safety issues", "Communications facilities" and "Water usage charging and efficiency devices".
- 4. As soon as possible after the tenant signs the agreement, the tenant must inspect the residential premises and complete the tenant section of the condition report. The tenant indicates agreement or disagreement with the condition indicated by the landlord or landlord's agent by placing "Y" (YES) or "N" (NO) in the appropriate column and by making any appropriate comments on the form. The tenant may also comment on the matters under the headings "Minimum standards", "Health issues", "Smoke alarms", "Other safety issues", "Communications facilities" and "Water usage charging and efficiency devices".
- The tenant must return one copy of the completed condition report, or a completed electronic copy, to the landlord or landlord's agent within 7 days after taking possession of the residential premises and is to keep the other copy or a completed electronic copy. The tenant is not required to do this if the landlord or landlord's agent has failed to give the tenant either two copies, or one electronic copy, of the completed condition report (see 2 above).
- 6. If photographs or video recordings are taken at the time the inspection is carried out, it is recommended that all photographs or video recordings are verified and dated by all parties. Any photographs should be attached to this condition report, in hard copy or electronically, under the heading "Photographs/video recordings of the premises". Any video recordings should be attached to this condition report electronically. NOTE: Photographs and/or video recordings are not a substitute for accurate written descriptions of the condition of the premises.
- 7. At, or as soon as practicable after, the termination of the tenancy agreement, both the landlord or the landlord's agent and the tenant should complete the copy of the condition report that the landlord, landlord's agent or the tenant has retained, indicating the condition of the premises at the end of the tenancy. This should be done in the presence of the other party, unless the other party has been given a reasonable opportunity to be present and has not attended the inspection.
- If the residential premises are separately metered for water and if the tenant is required to pay for water usage charges under the residential tenancy agreement, the landlord or landlord's agent must also indicate whether the residential premises has the required water efficiency measures.

Important notes about this report

- a) It is a requirement that a condition report be completed by the landlord and the tenant (see above). This condition report is an important record of the condition of the residential premises when the tenancy begins and may be used as evidence of the state of repair or general condition of the premises at the commencement of the tenancy. It is important to complete the condition report accurately. It may be vital if there is a dispute, particularly about the return of the rental bond money and any damage to the premises.
- b) At the end of the tenancy the premises will be inspected and the condition of the premises at that time will be compared to that stated in the original condition report.
- A tenant is not responsible for fair wear and tear to the premises. Fair wear and tear is a general term for anything that occurs through ordinary use, such as the carpet becoming worn in frequently used areas. Intentional damage, or damage caused by negligence, is not wear and tear.
- d) A condition report should be filled out whether or not a rental bond is paid.
- e) If you do not have enough space on the report attach additional pages. All attachments should be signed and dated by all parties to the residential tenancy agreement.
- Call Fair Trading on 13 32 20 or visit the website for information about the rights and responsibilities of landlords and tenants or before completing the condition report.

lample condition report	Com	dition of premises at START of to	//	./	1/2/25	dition of premions at EN	D of tenancy
	13/1/1	Landon's Agent Comments	1	-	3/1/1	Comments	1
Major disspraction design	INC DAINC		SC)		NOUS NO		17
medicinal type fronts	KEDSER	Epitipre feede	□	Spotowhoose	NOTE NO	poter hoose	71
Sylveylouser purels disprise?	DENDER		20		DVIVI DV		21
Southweiter	PUNDING.	promote man elector	200		21221		21

Lessor/agent's initial

Abma Date: 4 Sep 2023 Tenant/s initial

Maryolus

2.

3.

Date: 4 Sep 2023

Address of rental premises: 19 Van Kleef Circuit, Manly 2095

Tenants Name: Mrs Mary Lewis

Name of Landlord: Mark John
Lease Commencement Date: 29 Aug 2023

				Condition of premises at START of t	enano	су		Co	nditi	ion of premises at END of tenancy
	Clean	Undamaged	Working	Landlord / Agent Comments	Tenant agrees	Tenant Comments	Clean	Undamaged	Working	Comments Comments
Front Gardens				Garden neat and tidy. Lawn could do with weed spray and fertiliser.						Garden neat and tidy. Refer to media:
Driveway	N	Y	Y	Some oil stains which could be jet cleaned			Y	Y	Y	Drive clean of any oil stains
Paving	Y	Y	Y	Clear of weeds			Y	Y	Y	Looks good
Garden	Y	Y	Y	Black mulch laid which looks good			Y	Y	Y	Fresh Black mulch laid
Grass	Y	Y	Y	Mowed and edged			Y	Y	Y	Mowed but not edged
Verandah	Y	Y	Y	Gutter replaced last winter no further leaking reported			Y	Y	Y	No leaks
Letterbox/Street Number	Y	Y	Y	Numbering, clear and letterbox all good			Y	Y	Y	
Gutters/Downpipes	Y	Y	Y	Clear of leaves, no problems to report			N	Y	Y	Leaves need clearinf
Watering System	Υ	Y	Y	Retic needs to be serviced this summer			Y	Y	Y	Retic was serviced last summer.
Entry/Exterior				Render chipped on front pillar						Render repaired on front pillar Refer to media: 3
Door	Y	Y	Y	Frosting film installed on front door			Y	Y	Y	Frosting film installed on front door
Screen Door/Security Door	Υ	Y	Y	Secure and working			Y	Y	Y	Secure and working
Entry Lighting	Υ	Y	Y	Single downlights at entrance, tested and working			Y	Y	Y	Single downlights at entrance, tested and working
Bricks	Y	Y	Y	Issues with render on front pillar. Refer photo.			Y	Y	Y	Render repaired.

Lessor/agent's initial

Date: 4 Sep 2023

Tenant/s initial

Maryolum 2. 3. Date: 4 Sep 2023

Address of rental premises: 19 Van Kleef Circuit, Manly 2095

Name of Landlord: Mark John **Tenants Name:** Mrs Mary Lewis **Lease Commencement Date:** 29 Aug 2023

				Condition of premises at START of	tenand	Су		Co	nditi	ion of premises at END of tenancy
	Clean	Undamaged	Working	Landlord / Agent Comments	Tenant agrees	Tenant Comments	Clean	Undamaged	Working	Comments
Garage				Roller door working and three remotes tested						Roller door working and three remotes supplied and tested Refer to media: 4
Outside	Υ	Υ	Υ				Υ	Υ	Y	
Floor	Υ	Υ	Υ	Clean, no oil marks			Υ	Υ	Y	Clean, no oil marks
Walls	Y	Y	Υ				Y	Υ	Y	
Ceiling	Y	Y	Υ	No cobwebs			Y	Υ	Y	No cobwebs
Lighting	Υ	Y	Υ	Fluro light with cover			Y	Y	Y	Fluro light with cover
Points	Y	Y	Υ				Y	Y	Y	
Other	Υ	Υ	Υ				Y	Υ	Y	
Lounge				Neat and tidy						Neat and tidy Refer to media: 5
Door	Υ	Υ	Υ	Double doors painted white			Y	Y	Y	Double doors painted white
Floor	Y	Υ	Υ	Carpet freshly cleaned			N	Y	Y	Carpet has some stains could do with further cleaning
Skirting	Y	Y	Υ				Y	Υ	Y	
Walls	Υ	Y	Υ	Painted white			Y	Y	Y	Painted white
Blinds	Υ	Y	Y	Wiped clean			N	Y	Y	Need cleaning Refer to media: 6
Ceiling	Υ	Υ	Υ	Painted white with no marks			Υ	Υ	Υ	Painted white with no marks

Lessor/agent's initial

Agma Date: 4 Sep 2023

Tenant/s initial

Marydows

2.

Date: 4 Sep 2023

Page 3 of 15

Address of rental premises: 19 Van Kleef Circuit, Manly 2095

Tenants Name: Mrs Mary Lewis

Name of Landlord: Mark John Lease Commencement Date: 29 Aug 2023

				Condition of premises at START of te	nanc	zy .		Coi	nditi	on of premises at END of tenancy	
	Clean	Undamaged	Working	Landlord / Agent Comments	Tenant agrees	Tenant Comments	Clean	Undamaged	Working	Comments	Tenant agrees
Lighting	Y	Υ	Υ	4 down lights all working, dimmer working			Υ	Y	N	2 down lights not working	
Points	Y	Υ	Y				Y	Y	Y		
Corded Blinds and Window Coverings	Υ	Υ	Y				Υ	Υ	Y		
Windows/Window Safety Devices	Υ	Y	Y				Y	Y	Y		
Ceiling Fan/Air Conditioner	Y	Υ	Y	Tested and working			Y	Y	Υ	Tested and working	
Other	Y	Y	Y				Y	Y	Y		
Bathroom 1				Clean and tiles wiped clean						Clean and tiles wiped clean	
Door	Y	Υ	Y	Towel hook behind door			Y	Y	Y	Towel hook behind door	
Floor	Y	Y	Y	Tiles clean			Y	Y	Y	Tiles clean	
Walls	Υ	Y	Y	Painted white			Y	Y	Y	Painted white	
Ceiling	Υ	Y	Y	freshly painted white			Y	Y	Y	freshly painted white	
Lighting	Υ	Y	Y				Y	Υ	Y		
Points	Υ	Υ	Y				Υ	Y	Y		
Windows/Window Safety Devices	Υ	Y	Y				Y	Y	Y		
Sink/Taps	Υ	Y	Y				Y	Y	Y		

Lessor/agent's initial

Date: 4 Sep 2023

Tenant/s initial

Marydeur

2.

Date: 4 Sep 2023

Page **4** of **15**

Address of rental premises: 19 Van Kleef Circuit, Manly 2095

Name of Landlord: Mark John **Tenants Name:** Mrs Mary Lewis **Lease Commencement Date:** 29 Aug 2023

				Condition of p	remises at STA	RT of ter	nanc	у		Co	nditi	ion of premise	es at END of tenanc	у
	Clean	Undamaged	Working	Landlord / A	gent Comments		Tenant agrees	Tenant Comments	Clean	Undamaged	Working		Comments	Tenant agrees
Toilet	Υ	Y	Y						Υ	Y	Y			
Shower/Bath/Taps	Υ	Υ	Υ						Y	Υ	Y			
Mirror/Cabinet/Vanity	Y	Y	Y						Y	Y	Y			
Towel Rails	Υ	Y	N	Rail loose, handle requires tigh	ntening				Y	Y	Y	Rail handle fixe	ed	
Toilet Roll Holder	Υ	Y	Y						Y	Y	Y			
Heating/Exhaust Fan/Vent	Y	Y	Y	Tested and working					Y	Y	N	Heating bulb n	ot working	
Corded Blinds and Window Coverings	Y	Υ	Y						Υ	Y	Y			
Other	Y	Υ	Y						γ	Y	Y			
Bathroom 2				A lovely inspection, no p	roblems to report							A lovely inspec	tion, no problems to	
Door	Y	Y	Y						Υ	Y	Y			
Floor	Y	Y	Y						Y	Y	Y			
Walls	Y	Y	Υ						Y	Y	Y			
Ceiling	Υ	Υ	Y						Y	Y	Y			
Lighting	Υ	Υ	Υ						Y	Y	Y			
Points	Υ	Υ	Y						Y	Y	Y			
Lessor/agent's initial	Jenna	<u> </u>	1	Date: 4 Sep 2023	Tenant/s initial	Marydeur	S	2. 3.			[Date: 4 Sep 2023	Page 5	5 of 15

Address of rental premises: 19 Van Kleef Circuit, Manly 2095

Tenants Name: Mrs Mary Lewis

Name of Landlord: Mark John Lease Commencement Date: 29 Aug 2023

				Condition of premises at START of ter	nanc	су		Coi	nditi	on of premises at END of tenancy	
	Clean	Undamaged	Working	Landlord / Agent Comments	Tenant agrees	Tenant Comments	Clean	Undamaged	Working	Comments	Tenant agrees
Windows/Window Safety Devices	Y	Υ	Y				Y	Υ	Y		
Sink/Taps	Y	Y	Y				Y	Y	Y		
Toilet	Y	Υ	Y				Y	Υ	Υ		
Shower/Bath/Taps	Y	Υ	Y				Y	Υ	Υ		
Mirror/Cabinet/Vanity	Y	Υ	Y				Y	Υ	Υ		
Towel Rails	Y	Υ	Y				Y	Υ	Υ		
Toilet Roll Holder	Y	Υ	Y				Y	Υ	Υ		
Heating/Exhaust Fan/Vent	Y	Υ	Y				Y	Y	Y		
Corded Blinds and Window Coverings	Y	Y	Y				Y	Y	Y		
Other	Y	Y	Y				Y	Y	Y		
Bedroom 1				Neat and tidy						Neat and tidy	
Door	Y	Υ	Y	painted white			Y	Υ	Y	painted white	
Floor	Y	Υ	Y	carpet clean, no stains			Y	Υ	Υ	carpet clean, no stains	
Lighting	Y	Y	Y	tested and working			Y	Υ	Y	tested and working	
Windows/Window Safety Devices	N	Υ	Y	Windows need cleaning			N	Y	Y	Windows need cleaning	

Lessor/agent's initial

Date: 4 Sep 2023

Tenant/s initial

Maryceus 2.

Date: 4 Sep 2023

Page **6** of **15**

Address of rental premises: 19 Van Kleef Circuit, Manly 2095

Tenants Name: Mrs Mary Lewis

Name of Landlord: Mark John Lease Commencement Date: 29 Aug 2023

				Condition of premises at START of ter	nan	су		Coi	ndition of premises at END of tenancy
	Clean	Undamaged	Working	Landlord / Agent Comments	Tenant agrees	Tenant Comments	Clean	Undamaged	Tenant agrees Comments
Bedroom 2									
Door	Y	Y	Y				Y	Y	Υ
Floor	Υ	Y	Y				Y	Υ	Υ
Skirting	Y	Y	Y				Y	Υ	Y
Walls	Y	Y	Y				Y	Υ	Y
Ceiling	Υ	Y	Y				Y	Υ	Y
Lighting	Y	Y	Y				Y	Υ	Y
Points	Y	Y	Y				Y	Υ	Υ
Corded Blinds and Window Coverings	Υ	Y	Y				Y	Υ	Υ
Wardrobe/Drawers/ Shelves	Y	Y	Y				Y	Y	Y
Windows/Window Safety Devices	Y	Y	Y				Y	Υ	Y
Ceiling Fan/Air Conditioner	Y	Y	Y				Y	Υ	Y
Other	Y	Y	Y				Y	Υ	Y
Bedroom 3									
Door	Y	Y	Y				Y	Υ	Y
Floor	Υ	Y	Y				Y	γ	Υ

Lessor/agent's initial

Date: 4 Sep 2023

Tenant/s initial

Marydous

2.

Date: 4 Sep 2023

Page **7** of **15**

Address of rental premises: 19 Van Kleef Circuit, Manly 2095

Tenants Name: Mrs Mary Lewis

Name of Landlord: Mark John
Lease Commencement Date: 29 Aug 2023

101141	110		1411.2	s Mary Lewis					cusc			tement bate. 29 Aug 2023	
				Condition of p	remises at START of te	nanc	у			Cor	nditi	on of premises at END of tena	ncy
	Clean	Undamaged	Working	Landlord / A	gent Comments	Tenant agrees	Tenant Comme	nts	Clean	Undamaged	Working	Comments	o
Skirting	Υ	Υ	Υ						Υ	Y	Υ		
Walls	Y	Υ	Υ						Υ	Y	Υ		
Ceiling	Y	Υ	Υ						Υ	Υ	Υ		
Lighting	Y	Υ	Υ						Υ	Υ	Υ		
Points	Y	Υ	Υ						Υ	Υ	Υ		
Corded Blinds and Window Coverings	Y	Υ	Y						Y	Y	Y		
Wardrobe/Drawers/ Shelves	Y	Y	Y						Y	Y	Y		
Windows/Window Safety Devices	Y	Υ	γ						Y	Y	Y		
Ceiling Fan/Air Conditioner	Y	Υ	Υ						Υ	Y	Y		
Other	Y	Υ	Υ						Υ	Y	Y		
Kitchen/Meals				Pantry sensor light, not scraping on floor	working and pantry door,							Pantry sensor light and door fixed	
Bench	Y	Υ	Y	No noted marks					Υ	Y	Y	No noted marks	
Oven	Y	Υ	Y	Well cleaned					Y	Y	Y	Well cleaned	
RHood	Y	Υ	Y	Free from grease					Y	Y	Y	Free from grease	
Pantry	Υ	N	N	Pant light sensor is not working	ng and the pantry door is scraping				Υ	Υ	γ	Pant light sensor is working and the	9

Address of rental premises: 19 Van Kleef Circuit, Manly 2095

Tenants Name: Mrs Mary Lewis

					Condition of p	remises at STA	RT of ten	anc	у		Coi	nditi	on of premises at END of tenan	су
	Clean	Undamaged	Working		Landlord / A	gent Comments		Tenant agrees	Tenant Comments	Clean	Undamaged	Working	Comments	Tenant agrees
					on the wooden floor. It require	es adjusting							pantry door is fixed	
Theatre Room					Carpet clean, no stains								Carpet showing signs of wear	
Door	Y	Y	Y	,	Double doors painted white					Y	Υ	Υ	Double doors painted white	
Floor	Y	Y	Y	,	Carpet has no stains					Y	Y	Y	Carpet showing signs of wear	
Walls	Y	Y	Y	,	No marks					Y	Υ	Y	No marks	
Ceiling	Y	Y	Y	,	Painted white					Y	Υ	Y	Painted white	
Lighting	Y	Y	Y	,	Dimmers installed					Y	Υ	Y	Dimmers installed	
Dining					A lovely inspection, no p	problems to report							A lovely inspection, no problems to report	
Door	Y	Y	Y	,						Y	Υ	Y		
Floor	Y	Y	Y	,						Y	Y	Y		
Skirting	Y	Y	Y	,						Y	Υ	Y		
Walls	Υ	Y	Y	,						Y	Υ	Υ		
Ceiling	Υ	Y	Y	,						Y	Υ	Y		
Lighting	Υ	Y	Y	,						Y	Y	Υ		
Points	Υ	Y	Y	,						Y	Υ	Y		
Windows/Window Safety Devices	Y	Y	Y	,						Y	Υ	Y		
Lessor/agent's initial	Jenns				Date: 4 Sep 2023	Tenant/s initial	Marydows)	2. 3.			D	Page	e 9 of 15

Name of Landlord: Mark John

Lease Commencement Date: 29 Aug 2023

Address of rental premises: 19 Van Kleef Circuit, Manly 2095

Name of Landlord: Mark John **Tenants Name:** Mrs Mary Lewis **Lease Commencement Date:** 29 Aug 2023

				Condition of p	remises at STA	RT of ten	anc	у			Cor	ıditi	on of premis	es at END of tenanc	y
	Clean	Undamaged	Working	Landlord / A	gent Comments		Tenant agrees	Tenant Comment	ts	Clean	Undamaged	Working		Comments	Tenant agrees
Corded Blinds and Window Coverings	Υ	Υ	Υ							Y	Υ	Υ			
Ceiling Fan/Air Conditioner	Y	Y	Υ							Y	Y	Y			
Other	Y	Y	Υ							Y	Y	Y			
Toilet				No problems to report									Cistern keeps Needs servicir	running after flushing.	
Door	Y	Υ	Υ							Y	Y	Y			
Floor	Y	Y	Υ							Y	Y	Y			
Walls	Y	Y	Υ							Y	Υ	Y			
Toilet	Y	Y	Υ							Y	Y	N	Cistern helps	running after flushing	
Roll Holder	Y	Υ	Υ							Y	Y	Y			
Ceiling	Y	Υ	Υ							Y	Υ	Y			
Lighting	Y	Υ	Υ							Y	Υ	Y			
Windows/Window Safety Devices	Y	Y	Y							Y	Y	Y			
Sink	Y	Y	Y							Y	Y	Y			
Corded Blinds and Window Coverings	Y	Υ	Υ							Y	Y	Y			
Other	Y	Υ	Υ							Υ	Y	Υ			
essor/agent's initial	, Gama)			Date: 4 Sep 2023	Tenant/s initial	Maryden	Λ	2.	3.			D	ate: 4 Sep 2023	Page 1	0 of 15

Address of rental premises: 19 Van Kleef Circuit, Manly 2095

Name of Landlord: Mark John **Tenants Name:** Mrs Mary Lewis **Lease Commencement Date:** 29 Aug 2023

				Condition of premises at START of te	nand	су		Coi	nditi	on of premises at END of tenancy	
	Clean	Undamaged	Working	Landlord / Agent Comments	Tenant agrees	Tenant Comments	Clean	Undamaged	Working	Comments	Tenant agrees
Laundry				The paint is peeling along the walls, this indicates damp from dryer, as it is not ventilated.						Wall painted, looks good. Trough still rusty Refer to media: 7	
Walls	Y	Y	Y	Paint peeling and requires repainting			Y	Y	Y	Paint peeling and requires repainting	
Trough	Y	N	Y	Showing signs of rust			Y	N	Y	Still rusty, needs replacing	
Rear Gardens				Neat and tidy						Neat and tidy. Pool water feature render is peeling Refer to media: 8 9	
Paving	Y	Y	Y	Clear of weeds			Y	Υ	Y	Clear of weeds	
Grass	Y	Y	Y	Some holes where the dog has dug, but otherwise very neat the grass has been mowed and edged.			Y	Y	Y	Some holes where the dog has dug, but otherwise very neat the grass has been mowed and edged.	
Security/Safety				Security doors or working						Security doors or working	
				House alarm tested and working						House alarm tested and working	
Smoke Alarms	Y	Y	Y	tested and working			Y	Y	Y	tested and working	
RCD/Safety Switch	Y	Y	Y	Compliant with regulations			Y	γ	Y	Compliant with regulations	

Agma

Tenant/s initial

Address of rental premises: 19 Van Kleef Circuit, Manly 2095

Tenants Name: Mrs Mary Lewis

Name of Landlord: Mark John
Lease Commencement Date: 29 Aug 2023

Minimum Standards The landlord must indicate whether the following apply to the premises:				Health issues The landlord must indicate whether the following apply to the premises:		
 Note: Premises are structurally sound only if the floors, ceilings, walls, supporting structures (including foundations), doors, windows, roof, stairs, balconies, balustrades and railings are (i) in a reasonable state of repair, and (ii) are not liable to collapse because they are rotted or otherwise defective, and floors, ceiling, walls and supporting structures are not subject to significant dampness, and roof, ceilings and windows do not allow water penetration into the premises. 				b) Are there any pests and vermin?		No
				c) Has any rubbish been left on the premises?		No
				d) Are the premises listed on the Loose-Fill Asbestos Insulation Register?		No
2. Does the premises have adequate:				Smoke Alarms		
a) natural or artificial lighting in each room (excluding storage rooms or garages)?b) ventilation?			Yes	The landlord must indicate the following:		
			Yes	Have smoke alarms been installed in in accordance with the Environmental Act 1070 (including any significance).	Yes	
c) electricity outlet sockets or gas outlet sockets for the supply of lighting and heating to the premises, and for the use of appliances in the premises?d) plumbing and drainage?			Yes	Act 1979 (including any regulations made 2. Have all the smoke alarms installed of		
				checked and found to be in working order?		Yes
			Yes	Date last checked		1/9/23
Jtilities: 3. Are the premises: a) supplied with electricity?			Yes	3. Have the removable batteries in all the smoke alarms been replaced within the last 12 months, except for removable lithium batteries?		Yes
b) supplied with gas?			No	Date batteries were last changed:		1/3/23
c) connected to a water supply service or infrastructure that supplies water (including, but not limited to, a water bore or water tank) that is able to supply to the premises hot and cold water for drinking and ablution and cleaning activities?			Yes	4. Have the batteries in all the smoke alarms that have removeable lithium battery been replaced in the period specified by the manufacturer of the smoke alarm?		Yes
4. Does the premises contain bathroom facilities, including toilet and washing facilities that allow privacy for the user?			Yes	Date batteries were last changed:		1/3/23
5. Does the tenant agree with all the above? If no, specify which items?			Yes	Note: Section 64 of the Residential Tenancies Act 2010 provides that repairs to a smoke alarm includes maintenance of a smoke alarm in working order by installing or replacing a battery in the smoke alarm.		
.essor/agent's initial	Jona	Date: 4 Sep 2023	Tenant/s initial) 2. 3.	Date: 4 Sep 2023	Page 12 of 15

Address of rental premises: 19 Van Kleef Circuit, Manly 2095 Name of Landlord: Mark John **Tenants Name:** Mrs Mary Lewis **Lease Commencement Date:** 29 Aug 2023 Other Safety Issues Water Usage Charging and Efficiency Devices (Continued) The landlord must indicate whether the following apply to the premises: Date the premises were last checked to see it its No 1. Are there are any visible signs of damaged appliances (if appliances 1/3/2020 compliant with the water efficiency measures: are included as part of the tenancy)? Water meter reading at START of tenancy: Lph 2. Are there any visible hazards relating to electricity (eg. A loose or No damaged electricity outlet socket, loose wiring or sparking power Date of reading: points)? No 3. Are there any visible hazards relating to gas (eg. A loose or Water meter reading at END of tenancy: Lph damaged gas outlet socket or an open-ended gas pipe or valve? Wednesday, 28 August Date of reading: 4. Does the tenant agree with all the above? Yes 2024 If no, specify which items? Additional comments on minimum standards, health issues, smoke alarms, other safety issues, communication facilities, water usage charging and efficiency devices [May be added **Communication facilities** by landlord or tenant, or both) The landlord must indicate whether the following facilities are available: a telephone line is connected to the residential premises Yes an internet line is connected to the residential premises Yes **Water Usage Charging and Efficiency Devices** [only applicable if tenant pays water usage charges for the residential premises] 1. Are the residential premises separately metered? No Approximate dates when work last done on residential premises 2. The Landlord must indicate the following: 1/3/2020 Installation, repair or maintenance of smoke alarms all showerheads have a maximum flow rate of 9 litres per Yes minute 1/3/2023 on and from 23rd March 2025, all toilets are dual flush toilets Painting of premises (external): Yes with a minimum 3 star rating in accordance with the WELS scheme 1/3/2023 Painting of premises (internal): all internal cold water taps and single mixer taps in kitchen Yes sinks or bathroom hand basins have a maximum flow rate of Flooring laid/replaced/cleaned: 2018 9 litres per minute the premises have been checked and any leaking taps or No toilets on the residential premises have been fixed Marydons Lessor/agent's initial Apma Date: 4 Sep 2023 Tenant/s initial 3. Date: 4 Sep 2023 Page 13 of 15

Address of rental premises: 19 Van Kleef Circuit, Manly 2095

Tenants Name: Mrs Mary Lewis

Lease Commencement Date: 29 Aug 2023

Name of Landlord: Mark John

Landlord/agent's signature:

Date: 4 Sep 2023

Tenant's signature:

Date: 4 Sep 2023

Landlord's promise to undertake work: [Delete if not required]

The landlord agrees to undertake the following cleaning, repairs, additions or other work

during the tenancy: Yes

The landlord agrees to complete that work by: Mar 2024

Tenant/s initial

Marydours

3.

Date: 4 Sep 2023

Address of rental premises: 19 Van Kleef Circuit, Manly 2095

Tenants Name: Mrs Mary Lewis

View your photos/videos online via Gallery Link

Media

Front Gardens: Photo: (1) Taken: 26/06/2023



Lounge: Photo: (5) Taken: 01/09/2023



Rear Gardens: Video: (9) Taken: 09/08/2023



Front Gardens: Video: (2) Taken: 01/09/2023



Lounge - Blinds: Photo: (6) Taken: 01/09/2023



Entry/Exterior: Photo: (3) Taken: 01/09/2023



Laundry: Photo: (7) Taken: 01/09/2023



Garage: Photo: (4) Taken: 07/07/2022

Name of Landlord: Mark John

Lease Commencement Date: 29 Aug 2023



Rear Gardens: Photo: (8) Taken: 09/08/2023





Lessor/agent's initial

Abuna Date: 4 Sep 2023

